



6390 Joyce Drive
#100
Golden, CO 80403

PHONE 303-940-0033
FAX 303-940-0043
www.wibby.com

Instructions for: *WS Minerals (cat # PT-MIN-WS)*

SCOPE AND APPLICATION

Wibby Environmental's WS Minerals Proficiency Testing Standard is designed to be used with promulgated EPA methods as well as applicable methods from consensus organizations such as AWWA and ASTM. If you have any questions about the use of these standards, please contact Wibby Environmental Customer Service at 303-940-0033.

SAMPLE PREPARATION AND ANALYSIS

1. For best results, the PT standard should be stored near room temperature (~ 20°C).
2. The standard is ready for preparation and analysis as received. No dilution is required.

REPORTING RESULTS

1. Report results to three significant figures.
2. Report your results on line at www.wibby.com. Click on either the "Online Data Entry" or "PT Manage" link.
3. You may also report your results using the Data Reporting Sheets enclosed with your standards. FAX your results to Wibby Environmental at 303-940-0043 or mail the results to Wibby Environmental, 6390 Joyce Drive, #100, Golden, CO, 80403.
4. Wibby Environmental must receive all results prior to the study closing date shown on the Data Reporting Sheets.

SAFETY

These standards are designed for use by laboratory professionals who are familiar with handling environmental reference materials as well as hazardous materials. If you have any questions about the safe handling of these standards or require a Material Safety Data Sheet (MSDS,) please contact Wibby Environmental at 303-940-0033.

QUESTIONS?

If you have any questions regarding these standards or reporting requirements, please call Wibby Environmental at 303-940-0033.

NOTE: *Corrosivity* is determined using the WS Minerals standard. Determine all Corrosivity analytes (alkalinity, calcium, pH and total dissolved solids) in the WS Minerals standard. Do not use any other WS sample (e.g., WS pH) when determining Corrosivity. Calculate and report Corrosivity at 25°C.